

579 and 585 S Main Ave.

CONTRIBUTING



Sonoran row house style. Exposed stabilized adobe with parapet with brick coping. Wall height 14 ft. Tall window and door heights. Wood and metal gates. Tall wood double hung windows. Small square wood windows.

530 S. 4th Avenue CONTRIBUTING



Parapet territorial style with stucco wall finish. Wall height 12 ft. Double hung wood windows and smaller wood windows. Row house type setback.

448 S. Main Avenue CONTRIBUTING



Sonoran style with sloped parapet (Art Deco) Stucco wall finish. Wall height 12 ft. Double hung wood windows. Row house setback. Wrought iron fence.

586 S. Main Ave. CONTRIBUTING



Bungalow style, smooth stucco finish with double hung windows with wood trim. Porch and house with gable roof with corrugated metal roofing.

628 N 3rd Avenue Unit 1 and 2 CONTRIBUTING



Sonoran style with Gable roof (abandoned) Exposed mud adobes distressed wood double hung window no doors. windows . Gable roof with corrugated metal roofing

628 N 3rd Avenue Unit 1 and 2

CONTRIBUTING



Bungalow style with simple wood details. Stucco wall finish. Gable roof with asphalt shingle roofing. Wood double hung windows.

541 S Main Avenue CONTRIBUTING



Sonoran style with Gable roof (abandoned) Exposed mud adobes no windows . Gable roof with corrugated metal roofing.

537 S Main Ave. CONTRIBUTING



Mission style with parapet on both porch and main house with stucco wall finish. Wood double hung windows. Masonry patio wall with columns and arched entrance, stucco finish.

531 S Main Avenue CONTRIBUTING



*Sonoran style with simple wood shed roof porch
Stucco wall finish. Parapet roof. Wall height 11 ft.
Wood double hung windows. Wrought iron fence.*

517 S Main Avenue CONTRIBUTING



Sonoran style with stucco wall finish. Simple gable roof with asphalt shingle roofing. Row house setback and entry. Wood double hung windows with stucco sill.

517 S. Main Avenue (Unit 2) CONTRIBUTING



Sonoran style with simple gable roof. Stucco wall finish. Manufactured metal porch.

517 S. Main Avenue (unit 1) CONTRIBUTING



Bungalow style with simple plaster details. Stucco wall finish. Porch and Main House have different sloped gable roofs with asphalt shingle roofing. Double hung windows with stucco sills.

622 N. 3rd Ave. unit 1 and 2 CONTRIBUTING



Territorial style with and stucco wall finish. Gable roof with exposed rafter overhang and asphalt shingle roofing. Gable end siding.

562 S. Main Avenue CONTRIBUTING



Simple territorial style with stucco finish. Double hung wood windows with stucco sills. Hip roof with corrugated metal roofing.

570 S. Main Avenue CONTRIBUTING



Bungalow style with simple details and stucco finish .
Two story with high windows and dormers. Gable roof
with metal roofing.

580 S. Main Avenue CONTRIBUTING



*Territorial style with exposed smooth stucco finish
Double hung wood windows. Porch with gable roof and
attic vent. Gable roof with asphalt shingles*

582 S. Main Avenue CONTRIBUTING



Bungalow Style with smooth trowel stucco finish. Porch and Main house with Gable roof and asphalt shingles. Double hung wood windows with wood trim. Masonry patio wall.

584 S. Main Avenue CONTRIBUTING



Bungalow Style with smooth trowel stucco finish. Porch and Main house with Gable roof. Double hung wood windows Wood picket fence