EXHIBIT Q

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 5000* B4

AGENCY Tucson Police QA SPECIALIST Irene Doran
(Print Name)
INTOXILYZER SERIAL # 64-002659 (#13) LOCATION LAB
DATE January 29 ~~19~~ 2004 TIME 1756

_____ Display reads "READY TO START" or "PUSH BUTTON TO START TEST."

DIAGNOSTIC TESTS

_____ DVM Test check. Setting should be between .200 and .600. Mode selection switch S2 on, S1 and S3 off or keyboard menu selection "H". Reading is 0.374.
_____ Display Test check. Mode selection switch S1 on and S2 and S3 off or keyboard menu selection "V".
_____ Printer Test check. Mode selection switch S1, S2, S3 off or keyboard menu selection "P".
_____ Clock time check. Mode selection switch S10 on or keyboard menu selection "E".
_____ Date check. Mode selection switch S11 on or keyboard menu selection "E".

OPERATIONAL TESTS

_____ Alcohol free subject Test result 0.000 AC
_____ Error recognition logic system functioning
Invalid test printed
_____ Proper sample recognition system
Invalid sample printed
Deficient sample printed
N/A Completeness of sample purge with collection tube**
_____ Calibration standard 0.080 AC
Results: 0.071AC + 0.072AC

Instrument operating properly and accurately. YES ✓ NO__

COMMENTS: _____

SIGNATURE Irene Doran

0.080 alcohol concentration standard collected for subsequent analysis.**

*WITH OR WITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD
**THIS STEP IS ONLY REQUIRED IF THIS DEVICE IS BEING USED FOR SAMPLE CAPTURE.

DHS/DSLS/Form C117(Rev.7-93)

#13

```
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
EEEEEEEEEEEEEEEEEEEEEEEEEEEEE
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
HHHHHHHHHHHHHHHHHHHHHHHHHHHHH
0307 |--------------------------
0306 |--------------------------
0305 |--------------------------
0302 |--------------------------
0303 |--------------------------
0304 |--------------------------
0301 |--------------------------
```

SUBJECT'S NAME

TIME FIRST OBSERVED LAB INSTRUMENT LOCATION

DORAN (46331)
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

CMI INC

#13

```
FEDERAL SIGNAL CORP. / CMI INC
INTOXILYZER - ALCOHOL ANALYZER
AZ MODEL 5000    SN 64-002659
01/29/04

TEST              BAC VALUE   TIME

AIR BLANK            .000     18:28
SUBJECT TEST         .000     18:30
AIR BLANK            .000     18:30
```

DVM = 0.374

DORAN
SUBJECT'S NAME

TIME FIRST OBSERVED LAB INSTRUMENT LOCATION

DORAN 46331
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

CMI INC

#13

FEDERAL SIGNAL CORP. / CMI INC
INTOXILYZER — ALCOHOL ANALYZER
AZ MODEL 5000 — SN 64-002659
01/29/04

TEST	BAC VALUE	TIME
AIR BLANK	.000	18:32
CAL. CHECK	.071	18:32
AIR BLANK	.000	18:33

SUBJECT'S NAME

TIME FIRST OBSERVED

LAB
INSTRUMENT LOCATION

DORAN (46331)
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

CMI INC

#13

FEDERAL SIGNAL CORP. / CMI INC
INTOXILYZER — ALCOHOL ANALYZER
AZ MODEL 5000 — SN 64-002659
01/29/04

TEST	BAC VALUE	TIME
AIR BLANK	.000	18:33
CAL. CHECK	.072	18:34
AIR BLANK	.000	18:34

SUBJECT'S NAME

TIME FIRST OBSERVED

LAB
INSTRUMENT LOCATION

DORAN (46331)
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

CMI INC

Tucson Police Department Crime Laboratory

P 396

P.496

#13 01/29/04
18:45

E47.02
INVALID TEST-
SAMPLE INTRODUCED
AT IMPROPER TIME.

DORAN
SUBJECT'S NAME

4AB
INSTRUMENT LOCATION

TIME FIRST OBSERVED

DORAN 46331
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

CMI INC.

INTOXILYZER® INSTRUMENT PRINTER CARD

© 1986 by CMI INC.

p. 5 of 6

EXHIBIT P

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 5000*

TSG

STANDARD CALIBRATION CHECK PROCEDURE

Agency Tucson Police Department Date 1/29/04 Time 1756
Intoxilyzer Serial #13 04 002659 Location LAB
QA Specialist Irene Doran
(Print Name)

1. Pour a standard alcohol solution of known value into a clean dry simulator jar and assemble the simulator. Insure that a tight seal has been made.
   Standard value: 0.080 AC
2. Turn on the simulator and allow the temperature to reach 34°C±.2°C.
3. Set Intoxilyzer mode selection in the ACA mode by switching mode selection switch #9 on or selecting "C" on keyboard menu.
4. Attach simulator to the simulator entrance port on the Intoxilyzer.
5. Intoxilyzer 5000 display reads "READY TO START" or "PUSH BUTTON".
6. Push Start Test button or press enter on keyboard.
7. Insert card in response to display.
8. Air blank completed.
9. Calibration check completed.
   Test results 0.071 AC & 0.072 AC
10. Air blank completed.
11. When display reads Test Complete remove evidence card. Attach the card to the completed checklist.
12. Return mode selection switch #9 to off position after all calibration checks are complete or type Q and enter on keyboard.

SIGNATURE Irene Doran

*WITH OR WITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD

DHS/DSLS/Form C116 (Rev.7-93)

#13

FEDERAL SIGNAL CORP. / CMI INC
INTOXILYZER — ALCOHOL ANALYZER
AZ MODEL 5000 — SN 64-002659
01/29/04

TEST	BAC VALUE	TIME
AIR BLANK	.000	18:49
INVALID SAMPLE	.XXX	18:49
AIR BLANK	.000	18:50

DORAN
SUBJECT'S NAME

LAB
INSTRUMENT LOCATION

TIME FIRST OBSERVED

DORAN (46331)
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

Binaca

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC.

#13

FEDERAL SIGNAL CORP. / CMI INC
INTOXILYZER — ALCOHOL ANALYZER
AZ MODEL 5000 — SN 64-002659
01/29/04

TEST	BAC VALUE	TIME
AIR BLANK	.000	18:45
*SUBJECT TEST	.064	18:47
AIR BLANK	.000	18:48

* DEFICIENT SAMPLE - VALUE PRINTED WAS HIGHEST OBTAINED.

DORAN
SUBJECT'S NAME

LAB
INSTRUMENT LOCATION

TIME FIRST OBSERVED

DORAN (46331)
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC.

P. 6 of 6