P. 10/16
flc

EXHIBIT Q

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 5000*

AGENCY Tucson Police QA SPECIALIST Jennifer Coombs 461160
(Print Name)

INTOXILYZER SERIAL # 66-001759 LOCATION ODD
DATE July 9 ~~19~~ 2004 flc TIME 1303

✓ Display reads "READY TO START" or "PUSH BUTTON TO START TEST."

DIAGNOSTIC TESTS

✓ DVM Test check. Setting should be between .200 and .600. Mode selection switch S2 on, S1 and S3 off or keyboard menu selection "H". Reading is .420.

✓ ** Display Test check. Mode selection switch S1 on and S2 and S3 off or keyboard menu selection "V".

✓ Printer Test check. Mode selection switch S1, S2, S3 off or keyboard menu selection "P".

✓ * Clock time check. Mode selection switch S10 on or keyboard menu selection "E".

✓ Date check. Mode selection switch S11 on or keyboard menu selection "E".

OPERATIONAL TESTS

✓ Alcohol free subject Test result 0.000 AC

✓ Error recognition logic system functioning
Invalid test printed

✓ Proper sample recognition system
Invalid sample printed ✓
Deficient sample printed ✓

N/A Completeness of sample purge with collection tube**

✓ Calibration standard 0.080 AC
Results: 0.086AC & 0.082AC

Instrument operating properly and accurately. YES ✓ NO __

COMMENTS: * moved clock ahead 1301 → 1304
** All character bars displayed, however display cycle sequence was disrupted.

SIGNATURE Jennifer L. Coombs

0. N/A alcohol concentration standard collected for subsequent analysis.**

*WITH OR WITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD
**THIS STEP IS ONLY REQUIRED IF THIS DEVICE IS BEING USED FOR SAMPLE CAPTURE.

DHS/DSLS/Form C117(Rev.7-93)

SN 66-001759 07/09/04/
E767.14 13:06/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
EEEEEEEEEEEEEEEEEEEEEEEEEEEEEEEE/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
HHHHHHHHHHHHHHHHHHHHHHHHHHHHHHH/
0307 |----------/
0306 |----------/
0305 |----------/
0302 |----------/
0303 |----------/
0304 |----------/
0301 |----------/

SUBJECT'S NAME

ODD

TIME FIRST OBSERVED INSTRUMENT LOCATION

46160

OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC

TUCSON POLICE DEPARTMENT
INTOXILYZER - ALCOHOL ANALYZER /
AZ MODEL 5000 SN 66-001759
07/09/04 13:14 /

TEST	BRAC VALUE	TIME
AIR BLANK	.000	13:13
SUBJECT TEST	.000	13:14
AIR BLANK	.000	13:14

DVM=.420

SUBJECT'S NAME

ODD

TIME FIRST OBSERVED INSTRUMENT LOCATION

46160

OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC

P. 26 of 26

TUCSON POLICE DEPARTMENT
INTOXILYZER - ALCOHOL ANALYZER /
AZ MODEL 5000 SN 66-001759
07/09/04 13:08 /

TEST	BRAC VALUE	TIME
AIR BLANK	.000	13:08
CAL. CHECK	.086	13:00
AIR BLANK	.000	13:08

SUBJECT'S NAME

TIME FIRST OBSERVED

ODD
INSTRUMENT LOCATION

46160
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC

TUCSON POLICE DEPARTMENT
INTOXILYZER - ALCOHOL ANALYZER /
AZ MODEL 5000 SN 66-001759
07/01/04 13:10 /

TEST	BRAC VALUE	TIME
AIR BLANK	.000	13:09
CAL. CHECK	.087	13:10
AIR BLANK	.000	13:10

SUBJECT'S NAME

TIME FIRST OBSERVED

ODD
INSTRUMENT LOCATION

46160
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC.

Tucson Police Department Crime Laboratory

P. 396

P. 496
file

SN 66-001759
E767.14
INVALID TEST

07/09/04/
13:15/

PRESSED START TEST AT
IMPROPER TIME

SUBJECT'S NAME

ODD

TIME FIRST OBSERVED

INSTRUMENT LOCATION

461 60

OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC

P. 5 of 6
file

EXHIBIT P

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 5000*

STANDARD CALIBRATION CHECK PROCEDURE

Agency Tucson Police Department Date 7/9/04 Time 1303
Intoxilyzer Serial# 66-001759 Location ODD
QA Specialist Jennifer Coombs 46160
(Print Name)

(✓) 1. Pour a standard alcohol solution of known value into a clean dry simulator jar and assemble the simulator. Insure that a tight seal has been made.
Standard value: 0.080 AC

(✓) 2. Turn on the simulator and allow the temperature to reach 34°C±.2°C.

(✓) 3. Set Intoxilyzer mode selection in the ACA mode by switching mode selection switch #9 on or selecting "C" on keyboard menu.

(✓) 4. Attach simulator to the simulator entrance port on the Intoxilyzer.

✓(✓) 5. Intoxilyzer 5000 display reads "READY TO START" or "PUSH BUTTON".

✓(✓) 6. Push Start Test button or press enter on keyboard.

✓(✓) 7. Insert card in response to display.

✓(✓) 8. Air blank completed.

✓(✓) 9. Calibration check completed.
Test results 0.086AC & 0.087 AC

✓(✓) 10. Air blank completed.

✓(✓) 11. When display reads Test Complete remove evidence card. Attach the card to the completed checklist.

(✓) 12. Return mode selection switch #9 to off position after all calibration checks are complete or type Q and enter on keyboard.

SIGNATURE Jennifer L. Coombs

*WITH OR WITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD

DHS/DSLS/Form C116 (Rev.7-93)

TUCSON POLICE DEPARTMENT
INTOXILYZER - ALCOHOL ANALYZER /
AZ MODEL 5000 SN 66-001759
07/09/04 13:11 /

TEST	BRAC VALUE	TIME
AIR BLANK	.000	13:10
INVALID SAMPLE	.MOA	13:18
AIR BLANK	.000	13:19

BEGIN NEW DEPRIVATION PERIOD

SUBJECT'S NAME

TIME FIRST OBSERVED

ODD
INSTRUMENT LOCATION

46160
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

Sweet Breath

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC.

TUCSON POLICE DEPARTMENT
INTOXILYZER - ALCOHOL ANALYZER /
AZ MODEL 5000 SN 66-001759
07/01/04 13:23 /

TEST	BRAC VALUE	TIME
AIR BLANK	.000	13:20
*SUBJECT TEST	.072	13:23
AIR BLANK	.000	13:23

* DEFICIENT SAMPLE - VALUE
PRINTED WAS HIGHEST OBTAINED.

SUBJECT'S NAME

TIME FIRST OBSERVED

ODD
INSTRUMENT LOCATION

46160
OPERATOR

ADDITIONAL INFORMATION AND/OR REMARKS

INTOXILYZER® INSTRUMENT PRINTER CARD

CMI INC

© 1986 by CMI INC.

P. 1 of 1
flc

TUCSON POLICE DEPARTMENT
CRIME LABORATORY

INTOXILYZER SERVICE RECORD

TBA

Date: 7/9/04
Intoxilyzer Serial Number: 66-001759
QAS: Jennifer Coombs 46160

Problem Description:
Pulled for preventative maintenance. All character bars displayed, however display cycle sequence was disrupted.

If the instrument is taken out of service, complete the following:

Date out of service 7/9/04

Calibration Check completed prior to removal from service:

☑ Yes Date: 07/9/04 ☐ No

SQAP completed prior to removal from service:

☑ Yes Date: 7/9/04 ☐ No

Date returned to service: 9/1/04

Corrective Action Taken or Repairs: