



CERTIFICATION by CUSTODIAN of RECORDS
 Tucson Police Department Crime Laboratory
 270 S. Stone Avenue Tucson, AZ 85701-1917

TSY
 10/26/2009

I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 8000 Serial Number 80-002345 maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.

A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC.

Date: 10/23/09 Cal 1 0.102 AC Cal 2 0.102 AC

Between the dates of 9/24/09 and 10/23/09 the instrument was operating properly and accurately.

The instrument was taken out of service for repair on -
 The instrument was returned to service on -

Sarah Cione

Sarah L. Cione

10/26/09

ADPS QAS Permit # 33355

SUBSCRIBED AND SWORN to before me this 26th day of October, 2009.

A. Hernandez

Notary Public



*Includes documents specified in A.A.C. R13-10-104.A.5

1 of 7 SC

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

TSY
10-26-2009

QA SPECIALIST Sarah Cione AGENCY Tucson Police Department

DATE 10/23/09 TIME 10:59

INTOXILYZER SERIAL # 80-002345 LOCATION Team 3

(✓) 1. Display reads "PUSH BUTTON TO START"

DIAGNOSTIC TESTS

- (✓) 1. Clock time check.
- (✓) 2. Date check.

OPERATIONAL TESTS

- (✓) 1. Alcohol-free subject test result 0. 000 AC.
- (✓) 2. Error recognition logic system functioning.
Not a Successfully Completed Test Sequence printed
- (✓) 3. Proper sample recognition system.
Not a Successfully Completed Test Sequence printed
Deficient sample printed.
- (✓) 4. Standard Calibration Check standard 0. 100 AC
Result: 0. 102 AC

Instrument is operating properly and accurately. YES NO

COMMENTS

SIGNATURE Sarah Cione

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

2 of 7
SC

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002345
10/23/2009

11:01:19

AS9

Standard Lot#: 826001I
Last Changed By: C. CONLEY #34517

OAS: S. CIONE #50616
TUCSON PD

Operator: S. CIONE #50616
TUCSON PD

Subject: SQAP, TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	11:02:02
Diagnostic Test	Pass	11:02:30
Air Blank	0.000	11:02:57
0.100 Cal Check	0.103	11:03:16
Air Blank	0.000	11:03:45
Subject Test	0.000	11:04:00
Air Blank	0.000	11:04:27
Five Minute Wait	ABT*	
Air Blank	0.000	11:05:02

*Sequence Aborted

Not a Successfully Completed Test Sequence

3 of 7
SC

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002345
10/23/2009 11:05:08

Standard Lot#: 826001I
Last Changed By: C. CONLEY #34517

QAS: S. CIONE #50616
TUCSON PD

Operator: S. CIONE #50616
TUCSON PD

Subject: SQAP,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

154

Test	g/210L	Time
Air Blank	RFI*	11:05:32
Air Blank	IPS**	11:05:40

*RFI Detect
**Improper Sample

Not a Successfully Completed Test Sequence

4 of 7
SC F SC

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002345
10/23/2009 11:05:44

Standard Lot#: 826001I
Last Changed By: C. CONLEY #34517

QAS: S. CIONE #50616
TUCSON PD

Operator: S. CIONE #50616
TUCSON PD

Subject: SQAP,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

134

Test	g/210L	Time
Air Blank	0.000	11:06:25
Diagnostic Test	Pass	11:06:52
Air Blank	0.000	11:07:20
0.100 Cal Check	0.103	11:07:38
Air Blank	0.000	11:08:08
Subject Test	0.027*	11:11:16
Air Blank	0.000	11:11:46
Air Blank	0.000	11:12:14
Subject Test	XXX**	11:12:28
Air Blank	0.000	11:13:00

*Deficient Sample
**Invalid Sample
Begin new deprivation period

Not a Successfully Completed Test Sequence

5 of 7 sc

109

INTOXILYZER 8000
Location: ARIZONA
Serial Number: 80-002345
10/23/2009 11:13:17

Standard Lot#: 8260011
Last Changed By: C. CONLEY #34517

QAS: S. CIONE #50616
TUCSON PD

Test	g/210L	Time
Air Blank	0.000	11:13:45
Cal Check	0.102	11:14:03
Air Blank	0.000	11:14:33

Sarah Cione
Operator's Signature

EXHIBIT G-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R13-10-104(A)

6 of 7 sc

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

754
10-26-09

QA Specialist Sarah Cione AGENCY Tucson Police Department
DATE 10/23/09 TIME 1059
Intoxilyzer Serial # 80-002345 Location Team 3

- (✓) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0. 100 AC.
OR
Pour a standard alcohol concentration solution _____ AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C
- (✓) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
- (✓) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
- (✓) 4. Air blank completed.
- (✓) 5. Calibration check completed. Test results 0. 102 AC.
- (✓) 6. Air blank completed.
- (✓) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE Sarah Cione

DPS Form Exh G-2 (Rev. 05-01)

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

INTOXILYZER 8000
Location: ARIZONA
Serial Number: 80-002345
10/23/2009

10:59:56

Standard Lot#: 8260011
Last Changed By: C. CONLEY #34517

QAS: S. CIONE #50616
TUCSON PD

Test	g/210L	Time
Air Blank	0.000	11:00:23
Cal Check	0.102	11:00:42
Air Blank	0.000	11:01:12

Sarah Cione

Operator's Signature

7 of 7 SC

BY