CERTIFICATION by CUSTODIAN of RECORDS

Tucson Police Department Crime Laboratory
270 S. Stone Avenue Tucson, AZ 85701-1917

TSH 6-10-09

I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 8000 Serial Number 80-002760 maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.

A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC.

Date: 06/04/09 Cal 1 0.100 AC Cal 2 0.101 AC

Between the dates of 05/07/09 and 06/04/09 the instrument was operating properly and accurately.

The instrument was taken out of service for repair on —.
The instrument was returned to service on —.

Cheryl K. Straub

Cheryl K. Straub

06/07/09

ADPS QAS Permit # 33408

SUBSCRIBED AND SWORN to before me this 9th, day of June, 2009.

A.M. Hernández

Notary Public

OFFICIAL SEAL
A.M. HERNÁNDEZ
NOTARY PUBLIC-ARIZONA
PIMA COUNTY
My Comm. Exp. Mar. 17, 2012

*Includes documents specified in A.A.C. R13-10-104.A.5

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

EXHIBIT G-4

1310 CS

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

TSH 6.10.09

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST Cheryl STRAUB AGENCY Tucson Police Department

DATE 06/04/09 TIME 07:31

INTOXILYZER SERIAL # 80-002760 LOCATION DUI HQ

(✓) 1. Display reads "PUSH BUTTON TO START"

DIAGNOSTIC TESTS

(✓) 1. Clock time check.
(✓) 2. Date check.

OPERATIONAL TESTS

(✓) 1. Alcohol-free subject test result 0. 000 AC.
(✓) 2. Error recognition logic system functioning.
Not a Successfully Completed Test Sequence printed
(✓) 3. Proper sample recognition system.
Not a Successfully Completed Test Sequence printed
Deficient sample printed.
(✓) 4. Standard Calibration Check standard 0. 100 AC
Result: 0. 101 AC

Instrument is operating properly and accurately. YES ✓ NO ____

COMMENTS When performing test for mouth Alcohol I was unable to blow correctly: I was Coughing. Test had to be Repeated. CS 50772 (pg. 4 and 5)

SIGNATURE Cheryl Straub

DPS Form Exh G-4 (Rev. 05-01)

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

~~298~~
CS
2310
CS

184

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002760
06/04/2009 07:37:56

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	07:39:03
Diagnostic Test	Pass	07:39:30
Air Blank	0.000	07:39:57
0.100 Cal Check	0.101	07:40:16
Air Blank	0.000	07:40:46
Subject Test	0.000	07:41:01
Air Blank	0.000	07:41:28
Five Minute Wait	ABT*	
Air Blank	0.000	07:42:03

*Sequence Aborted

Not a Successfully Completed Test Sequence

Pursuant to section 28-1527, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

~~3 of 8~~ CS
3710 CS

154

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002760
06/04/2009 07:43:13

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	RFI*	07:44:00
Air Blank	IPS**	07:44:08

*RFI Detect
**Improper Sample

Not a Successfully Completed Test Sequence

Pursuant to section 28-1527, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

~~448~~, 4810
CS CS

184

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002760
06/04/2009 07:45:36

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	07:46:41
Diagnostic Test	Pass	07:47:09
Air Blank	0.000	07:47:36
0.100 Cal Check	0.101	07:47:55
Air Blank	0.000	07:48:24
Subject Test	0.050*	07:51:33
Air Blank	0.000	07:52:04
Air Blank	0.000	07:52:32
Subject Test	0.081	07:52:48
Air Blank	0.000	07:53:22
Five Minute Wait	ABT**	
Air Blank	0.000	07:54:05

*Deficient Sample
**Sequence Aborted

FOR INVALID TEST
~~Residual~~ mouth Alcohol; test was not blowing properly;
CS Coughing CS 50772

Not a Successfully Completed Test Sequence

Pursuant to section 28-1527, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

5 of 10
CS

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002760
06/04/2009 07:54:14

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	07:55:14
Diagnostic Test	Pass	07:55:41
Air Blank	0.000	07:56:09
0.100 Cal Check	0.101	07:56:28
Air Blank	0.000	07:56:57
Subject Test	0.019	07:57:15
Air Blank	0.000	07:57:46
Five Minute Wait	ABT*	
Air Blank	0.000	07:59:13

*Sequence Aborted

For Invalid Test;
~~Recordgnt~~ mouth Alcohol test; Not blowing properly; Coughing
QS. 50772

Not a Successfully Completed Test Sequence

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

~~488~~
C8
6710
C8

TBY

INTOXILYZER 8000
Location: ARIZONA
Serial Number : 80-002760
06/04/2009 07:59:36

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRÄUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

---

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	08:00:40
Diagnostic Test	Pass	08:01:07
Air Blank	0.000	08:01:34
0.100 Cal Check	0.102	08:01:53
Air Blank	0.000	08:02:23
Subject Test	XXX*	08:04:13
Air Blank	0.000	08:04:46

*Invalid Sample
Begin new deprivation period

Not a Successfully Completed Test Sequence

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

~~588~~ CS
7810 CS
B4

INTOXILYZER 8000
Location: ARIZONA
Serial Number: 80-002760
06/04/2009 08:33:08

Standard Lot#: 7309011
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Operator: C. STRAUB #50772
TUCSON PD

Subject: TEST,TEST
DOB: 11/11/1111
Sex: F Weight: 111

---

15 Minute Deprivation Period? Yes

Test	g/210L	Time
Air Blank	0.000	08:34:05
Diagnostic Test	Pass	08:34:34
Air Blank	0.000	08:35:01
0.100 Cal Check	0.100	08:35:20
Air Blank	0.000	08:35:49
Subject Test	0.000	08:36:03
Air Blank	0.000	08:36:30
Five Minute Wait		
Air Blank	0.000	08:41:31
Subject Test	0.000*	08:44:39
Air Blank	0.000	08:45:08

*Deficient Sample

Not a Successfully
Completed
Test Sequence

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

~~6 8~~
C8
8 9 10
C8

134

INTOXILYZER 8000
Location: ARIZONA
Serial Number: 80-002760
06/04/2009 08:06:10

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Test	g/210L	Time
Air Blank	0.000	08:06:37
Cal Check	0.101	08:06:56
Air Blank	0.000	08:07:26

Cheyl Straub
Operator's Signature

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department

~~798~~
CS
9310
CS

EXHIBIT G-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY
A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES
INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

TBY
6.10.09

QA Specialist Cheryl STRAUB AGENCY Tucson Police Department

DATE 06/04/09 TIME 07:31

Intoxilyzer Serial # 80-002760 Location DUI H2

(✓) 1. Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0.100 AC.

OR

Pour a standard alcohol concentration solution _____AC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C ± 0.2°C

(✓) 2. Intoxilyzer 8000 display reads "PUSH BUTTON TO START"

(✓) 3. Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.

(✓) 4. Air blank completed.

(✓) 5. Calibration check completed. Test results 0.100 AC.

(✓) 6. Air blank completed.

(✓) 7. Remove printed record. Attach the record to the completed checklist.

SIGNATURE Cheryl Straub

DPS Form Exh G-2 (Rev. 05-01)

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

~~8 of 8~~
CS
10710
CS

134

INTOXILYZER 8000
Location: ARIZONA
Serial Number: 80-002760
06/04/2009 07:31:02

Standard Lot#: 730901I
Last Changed By: S. CIONE #50616

QAS: C. STRAUB #50772
TUCSON PD

Test	g/210L	Time
Air Blank	0.000	07:31:30
Cal Check	0.100	07:31:48
Air Blank	0.000	07:32:18

Cheryl Straub
Operator's Signature

Pursuant to section 28-1527, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department