



CERTIFICATION by CUSTODIAN of RECORDS
Tucson Police Department Crime Laboratory

1 of 2 sc
By
2-25-2008

I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 8000 Serial Number 80-001108 maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.

A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC.

Date: N/A Cal 1 N/A AC Cal 2 N/A AC

Between the dates of - and - the instrument was operating properly and accurately.

The instrument was taken out of service for repair on 2/1/08.
The instrument was returned to service on -.


Sarah Cione

Sarah L. Cione

2/12/08

ADPS QAS Permit # 33355

SUBSCRIBED AND SWORN to before me this 12, day of February, 2008.



Kathy A Kinney
Notary Public

*Includes documents specified in A.A.C. R13-10-104.A.5

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.



TUCSON POLICE DEPARTMENT
CRIME LABORATORY

2 of 2 SC
134

INTOXILYZER SERVICE RECORD

Date: 2/1/08

QAS: Sarah Cione

Intoxilyzer Serial Number: 80-001108

Reason For Service: Display front panel was getting stuck on 2nd Diagnostic test during a duplicate subject test. Test would finish, but not print out. When instrument turned off/on, display would take a while to go to "Not Ready Mode" - it would be stuck on "CMI, Inc".

Date Out of Service: 2/1/08

Calibration Check completed prior to removal from service

Date: not performed

SQAP completed prior to removal from service

Date: not performed

Corrective Action: Sent to CMI, Inc. (2/5/08)
COBRA Data downloaded prior to shipping



1 of 1 SC
B4

Return Material Authorization Form

This form **MUST** be completed and enclosed with item(s) being returned.
Failure to complete and return this form may cause delays in crediting / repairing.

1. Item(s) Returned: Instrument Supplies Other
(Note: please ship items in their original shipping container(s) or a similar protective box.)

2. Instrument Model: 8000 Serial Number 80-001108

3. Bill To Address: Finance / Accounts Payable Ship To Address: (NO PO BOXES)
P.O. Box 27450 Tucson Police Department
TUCSON, AZ 85726-7450 Crime Lab
270 S. Stone Ave
TUCSON, AZ 85701-1917

Customer # 105075
Name Terry Gallegos
Phone: (520) 791-4494 Fax: (520) 791-4642
Email: Terry.Gallegos@TucsonAZ.gov

4. Reason for Return: Note - If you are sending an item for repair, please give a detailed description of the problem. Please list any special instructions that you may have concerning this return. Note - Returns for credit may be subject to a 15% restocking charge.
Instrument front panel was getting "stuck" on 2nd Diagnostics Test during a duplicate subject test. Test would actually finish, but nothing would print. When instrument was turned off, then on, took a long time for "Not Ready Mode" to appear on display - was stuck on "EMI, Inc"

5. Purchase Order Number (attach a copy of P.O. if applicable) 20669

6. I Authorize All Repairs: Yes No

7. I Authorize Repairs Up To: \$ _____

8. I Require An Estimate Regardless of Cost Yes No

Note: An evaluation fee will apply to estimates that are not repaired.

9. Authorized By:
Terry Gallegos
Name (Please Print)
Terry Gallegos 2.1.2008
Signature Date

Pursuant to Section 28.1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.