



CERTIFICATION by CUSTODIAN of RECORDS  
Tucson Police Department Crime Laboratory

TS4  
3-17-08

I hereby certify that these documents are a true and correct copy of the periodic maintenance\* for the Intoxilyzer 8000 Serial Number 80-002262 maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.

A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC.

Date: 3/11/08 Cal 1 N/A AC Cal 2 N/A AC

Between the dates of N/A and N/A the instrument was operating properly and accurately.

The instrument was taken out of service for repair on 3/10/08.  
The instrument was returned to service on -

Sarah Cione

Sarah L. Cione

3/14/08

ADPS QAS Permit # 33355

SUBSCRIBED AND SWORN to before me this 14, day of March, 2008.



OFFICIAL SEAL  
KATHY A. KINNEY  
NOTARY PUBLIC-ARIZONA  
PIMA COUNTY  
My Comm. Exp. Sept. 4, 2008

Kathy A Kinney

Notary Public

\*Includes documents specified in A.A.C. R13-10-104.A.5

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.



TUCSON POLICE DEPARTMENT  
CRIME LABORATORY

1 of 25c  
734

INTOXILYZER SERVICE RECORD

Date: 3/10/08

QAS: Sarah Cione

Intoxilyzer Serial Number: 80-002262

Reason For Service: Instrument stopped during a test. Front display not coming up properly. Problem advised of by Officer Corie Nolan.

Date Out of Service: 3/10/08

Calibration Check completed prior to removal from service

Date: NO

SQAP completed prior to removal from service

Date: NO

Corrective Action:  Sent to CMI, Inc. (3/11/08)



# Service Evaluation Form

2 of 2  
SC

This form **MUST** be completed and enclosed with instrument to be serviced.  
Failure to complete and return this form may cause delays in service.

(Note: please ship items in their original shipping container(s) or a similar protective box.)

1. Contact information: Customer Number 105075 (contact Customer Service)

Name Terry Gallegos Phone: (520) 791-4499 x1443

Fax: (520) 791-4642 Email: Terry.Gallegos@TucsonAZ.gov

2. Bill to Address: Finance / Accounts Payable Ship to Address: Crime Lab  
P.O. Box 27450 TUCSON Police Dept.  
TUCSON AZ 85726-7450 270 S. Stone Ave  
TUCSON AZ  
85701-1917

3. Instrument Model: 8000 Serial Number 80-002262

4. Detailed Description of Problem: Note - Please list any special instructions that you may have concerning this return.  
Power supply board is causing a display problem.  
The instrument stopped during a test.

### Please Choose One of the following Options:

(A minimum evaluation fee of \$79.00 will apply to estimates that are not repaired.)

- Yes, I Authorize All Repairs
  - I Authorize Repairs Up To:  \$100  \$250  \$500  \$750  \$\_\_\_\_\_
- Purchase Order Number (attach a copy of P.O. if applicable) 20669

Authorized By:  
Terry Gallegos  
Name (Please Print)  
Terry Gallegos 3.11.2008  
Signature Date

No, Please send estimate before repairs are made.