

✓ **Speedway & Euclid Bus Stop – NW Corner (SunTran # 11163)**

ADA accessibility Score: 4.7 (if drive-cut used)

Ridership: boardings = 50, total = 169

Issue(s): Stop does not have a loading pad. Sidewalk is attached to curb

Solution(s): Create ADA bus stop pad 10' wide depth between two walkways



**Stop completed:** stop moved to west of sidewalk at house and extension to sidewalk completed to create concrete lift area approx. 10' wide by 8' deep

