

✓ St. Mary's @ Furr's Cafeteria (SW Bonita Ave) Bus Stop – SE Corner (SunTran # 13689)

ADA accessibility Score: 4

Ridership: boardings = 68, total = 77

Issue(s): Stop has gap between sidewalk and curb.

Note: Community (Public) ADA requested improvements

Solution(s): at a minimum fill gap between sidewalk and curb at least 5 ft wide – preferably 30' width. Connect gap-fill from bus stop to existing walkway from parking lot.



Completed: image 6/30/2010
 Concrete fill installed approximately 33' from bus stop sign to walkway from Furr's Cafeteria parking lot creating an 8' space at the sidewalk.

-> new pic 2/26/2011 sign placed in correct location

